

When artwork suffers from severe surface rust, the effect of the piece can be lost.

Restoration of artwork using a Nyalic[®] preparation process and coating the piece with Nyalic will return the artwork to a like-new appearance and protect the piece from further degradation.

This particular piece consists of over 100 Lotus blooms cast in stainless steel. The full biological crease and tiny cells are visible on each of the castings. Surrounded by bubbling water and mist, over time, the stainless steel oxidized. Using Nyalic's proprietary cleaners and our clear surface protectant, this piece of art was restored and is protected.

